



Place Evo on black circle.



Press and hold Evo's power button for 5 sec. until top light blinks white. Then, release the power button.



Evo spins, moves outside the circle, and blinks green when calibrated.



